

Dirt / moisture trap (all Stainless Steel)

These dirt / moisture traps are used to protect pneumatic calibration systems from dirt and oil. Any dirt and moisture can be seen through the inspection glass. Including filter unit. The unit is easy to drain by means of a drain plug.

Max. 200 bar
With sight glass

Includes:

Table standing frame

Sight glass to detect dirt or moisture

Drain plug

Filter

Set of adapters: 1 x $\frac{1}{8}$ "BSP

1 x $\frac{1}{4}$ "BSP

1 x $\frac{3}{8}$ "BSP

1 x $\frac{1}{2}$ "BSP

